


# 2019 Street Preservation Change Order

Public Works Department



A photograph of a street under construction. A yellow excavator is positioned on the right side of the frame, its arm extended towards the center. The street surface is uneven and appears to be in the process of being paved or repaired. In the background, there are some trees and a building. The overall scene suggests a major infrastructure project.

Change  
Order

Current  
Project

Project  
Benefits

Summary



**Supportive, Sustainable Infrastructure**

# Current Project



Map


Financials

Schedule

# 2019 STREET PRESERVATION PROJECT



Map



LEGEND	
	MILL & OVERLAY PER PLAN
	SLURRY SEAL
	CHIP SEAL
	HOT CHIP

# Change Order



Map

Financials

Schedule

## EXHIBIT 1: Additional Project Locations



## Map



1

Estimated 130 Tons of Hot Mix Asphalt via Mill Patching

LEGNED


#### Crack Seal, Asphalt Patching, & Seal Coats

#### Crack Seal & Asphalt Patching

### Large Patching Locations

# Map

## EXHIBIT 2: Additional Project Locations




2

Estimated 110 Tons of Hot Mix Asphalt  
via Mill Patching

# EXHIBIT 3: Additional Project Locations



Map



## Financials

ITEM	AMOUNT
Budget	\$2,551,382.00
Project Award	\$1,928,396.50
Fund Balance	\$622,985.50
Contribution of Funds	\$85,000.00
Change Order	\$467,000.00
Budget Balance	\$240,985.50

## Schedule

### TASK

### DATE

Crack Seals

February 1, 2020

Asphalt Patching

November 14, 2019

Seal Coats

August 1, 2020

# Project Benefits




Cost  
Savings

Increase  
Limits

Schedule

# Summary



Execute  
CO

Plan

Plan

Execute  
Change  
Order

Schedule  
Work

Commence  
Construction



**2019 Street Preservation  
Change Order  
Public Works Department**