
## Elmwood Cemetery Irrigation Modernization Project



## **Background Information**

- 2014 lightning strike damaged 18 valves/wire assemblies, 6 were repaired and were able to run
- and were able to run
  May 2020, Derecho uprooted 30+ trees at Elmwood Cemetery causing widespread landscape damage and damage to additional wiring leaving the cemetery with 20 non-operational irrigation valves
  Currently, Cemetery Staff has to turn on those 20 valves by hand during the work day because they cannot work by irrigation clock
  Purpose is to get irrigation repaired and running on irrigation clocks in the evening when patrons are not paying respects to their loved one's at the cemetery during the day
- Formal proposals were requested from qualified professionals to complete the project specified





	TOIR	Timeline	,																	
	GANT	T CHART																		
		City of Brighton - Elmwood Cer Jon Zin				Ко	ty Lan 13/1	fscape 8/2020												-
	W85			WITE a				WITEK 2			111K ;				WITE 4			WITTES		
	NUMBER	TASK TITLE	м	TI	V R	FM	TI	N R	FI	4 T	w	R F	м	T W	R	F	MT	W	R	F
	1	Trenching / Wiring / Grounding																		
	2.3	Trenching		101	1.5															_
	1.2	Wiring																		_
	1.3	Grounding																		_
	2.4	Restoration																		_
	2	Valve Replacements																		
	2.1	Excevation																		
	2.2	Installation																		
	2.3	Restoration																		
	3	Isolation Valve Installation																		
	3.5	Excavation		TΤ														1		
	3.2	Installation																		_
	3.2.1	Restoration																		
	4	Directional Boring																		
1 M	6.3	OnSte				_			-	_	_	_					_	_	_	-

